

# !! URGENT !!

Date: 14 May 2024

Subject: Kilimanjaro, Tanzania Kilimanjaro Intl (HTKJ) Multiple Approach Procedures

#### Procedure coding incorrect

Jeppesen NavData for cycle 2405, effective 16 May 2024, contains incorrect data for Kilimanjaro Intl; Kilimanjaro, Tanzania (HTKJ).

#### ILS X or LOC X Rwy 09:

- transitions Kilimanjaro One and Kilimanjaro Two: altitude at VOR "KV" should read 7000'
- IF should read CF09, coordinates should read S03 26 14.471 E036 53 24.546
- coordinates of waypoint FI09 should read S03 26 04.72 E036 57 10.82
- coordinates of waypoint 34LOC should read S03 25 56.71 E037 00 16.65
- coordinates of waypoint ML09 should read S03 25 51.02 E037 02 28.53

### ILZ Z Rwy 09:

- coordinates of waypoint FI09 should read S03 26 04.72 E036 57 10.82
- coordinates of waypoint 34LOC should read S03 25 56.71 E037 00 16.65
- coordinates of waypoint ML09 should read S03 25 51.02 E037 02 28.53

VOR Y Rwy 27: Maximum Altitude at Holding "KV" should read FL 110

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2406, effective 13 June 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere) E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.