

LATE SOURCE NOTIFICATION BULLETIN

NAVBLUE Reference: 2405-05L

Notification Published date: 09-05-2024

Product Affected: Navigation+

AIRAC Cycle: 2405

Effective Date: 16-05-2024

Region: SAM

Country: Argentina; Brazil

Subject: Multiple Aerodrome Changes

Source: ARGENTINA AIP SUPP A56-24 & BRAZIL ROTAER AMD D16/24

Please note that the following information was received too late to be incorporated into NAVBLUE databases for cycle 2405

Argentina AIP SUPP A56-24

CORDOBA/ ING. AER. A. L. V. TARAVELLA (SACO):

Airport Record: Mag var changed from 6W to 7W

RWY 01: Magnetic bearing changed from 005 to 006. RWY 19: Magnetic bearing changed from 185 to 186. RWY 05: Magnetic bearing changed from 049 to 051. RWY 23: Magnetic bearing changed from 229oto 231.

ROTAER AMD D16/24

FAZENDA BOM PASTOR (SWMH)

Airport Record

FAZENDA ZANCCHETIN (SWYX)

Airport Record

LAURO CARNEIRO DE LOYOLA (SBJV)

Airport Comms

AERODROMO NACIONAL DE AVIACAO (SBNV)

Airport Comms

Prefeito Orlando Marinho (SBTF)

RWY 15/33

Fazenda Oeste (SDK3)

Airport Record



LATE SOURCE NOTIFICATION BULLETIN

AGUIAS DE TRINDADE (SDL7)

Airport Record

Haras MGC (SIP4)

New heliport, Helipad

SEBASTIAO JOSE PEREIRA (SIPO)

Airport Record

Fazenda Argemira (SIR4)

New Airport

Fazenda N.S. Aparecida (SIS4)

New Heliport, Helipad

Fazenda Varnier (SJVA)

Airport Record, Airport Comms

Fort Aviação Agrícola (SN6I)

New Airport

Caju (SID2)

New heliport, helipad

FAZENDA CORTEZIA (SIDW)

Airport Record

FAZENDA PAU D'ALHO (SIHX)

Airport Record

RANCHO BELA VISTA (SNUV)

Airport Comms

Condomínio Fazenda da Grama (SSIZ)

Airport record, Helipad

AUTOS DO SANGUE (SSJS)

Airport Record

Barreirinhas (SSRS):

Airport Comms

These changes will be incorporated in NAVBLUE databases for cycle 2406