



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2601-05E

Notification Published date: 10-02-2026

Product Affected: Navigation+

AIRAC Cycle: 2601

Effective Date: 22-01-2026

Region: SPA

Country: New Zealand

Subject: Incorrect vertical angle on NZAA and NZRO RNP (AR) approaches

Source: AIRAC Amd 01/25

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2601

AUCKLAND (NZAA)

CAUTION: For the RNP (AR) U RWY 23L approach, the waypoint AA521 has been incorrectly applied a vertical angle of 3.00 degrees in **NAVBLUE** databases. The vertical angle should not be coded for this fix.

ROTORUA (NZRO)

CAUTION: For the NZRO RNP (AR) Z RWY 36 approach, no vertical angle has been coded on the waypoint RO764. The vertical angle of 3.20 degrees will be added to the **NAVBLUE** databases.

These changes will be incorporated in NAVBLUE databases for cycle 2603