



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 8 November 2023

Subject: Haikou, PR of China
Meilan (ZJHK)
ILS DME X Rwy 28
Cycle 2311

Procedure coding incorrect

Jeppesen NavData for cycle 2311, effective 02 November 2023, contains incorrect data for Meilan; Haikou, PR of China (ZJHK).

ILS DME X Rwy 28: Speed limit for missed approach turn to MLT VOR should read **205 knots**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2312, effective 30 November 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Haikou, PR of China (ZJHK) 11-12 chart dated 27 OCT 23 (effective 1 November 2023 1600Z) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.