



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 28 November 2023

Subject: Chisinau, Moldova
Chisinau Intl (LUKK)
Multiple SIDs
Cycle 2312

Procedure coding incorrect

Jeppesen NavData for cycle 2312, effective 30 November 2023, contains incorrect data for Chisinau Intl; Chisinau, Moldova (LUKK).

SIDs ANEDO 1W [ANED1W], LIPTA 1W [LIPT1W], LOBRO 1W [LOBR1W], POGAV 1W [POGA1W], SURAP 1W [SURA1W], TURSA 1W [TURS1W], TUVAP 1W [TUVA1W]: initial course should read 270° until D2.9 KIV, therefore procedures should not be used.

SIDs ERADA 1W [ERAD1W], MANRO 1W [MANR1W], NERIS 1W [NERI1W], NUNTA 1W [NUNT1W], UNIRA 1W [UNIR1W], VOLVO 1W [VOLV1W]: initial course should read 270° until D6.4 KIV, therefore procedures should not be used.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2313, effective 28 December 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

LUKK_2312