



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2509-03E

Notification Published date: 09-09-2025

Product Affected: Navigation+

AIRAC Cycle: 2509

Effective Date: 04-09-2025

Region: EUR

Country: United Kingdom

Subject: SOUTHAMPTON (EGHI) - Noise abatement procedures - incorrect course

Source: AIRAC Amd 10-25

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2509

SOUTHAMPTON (EGHI)

CAUTION: The following noise abatement procedures have an incorrect course of 217 in NAVBLUE databases for the RWY 20 transition on the FA leg from SAM (VHF). The correct course should read 215:

SID EAST
SID NORTH
SID N WEST1
SID N WEST2
SID SOUTH

These changes will be incorporated in NAVBLUE databases for cycle 2510