



JEPPESSEN®

Airport Moving Map Alert

!! URGENT !!

Date: 31 July 2026

Subject: Buenos Aires, Argentina
Ezeiza Intl/Ministro Pistarini (SAEZ)
Cycle 2607

RWY 17/35 status incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2607, effective 09 July 2026, contain incorrect data for Ezeiza Intl/Ministro Pistarini; Buenos Aires, Argentina (SAEZ). Argentina AIP SUP A65/2026, published 06 March 2026, effective 01 August 2026, introduces closure of RWY 17/35 due to maintenance work. The following change (effective 01 August 2026) is not reflected in cycle 2607 data:

- **RWY 17/35 is closed**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE
TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2608, effective 06 August 2026. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

SAEZ_2607