AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2611-02E

Notification Published date: 30-10-2026

Product: Navigation

Database Type:

AIRAC Cycle: 2611

Effective Date: 29-10-2026

Region: MES

Country: India

Subject: KHAJURAHO (VEKO) - ILS, LOC, VOR , NDB RWY 19 approach transitions incorrect

Source: AIRAC Supp 183/26

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2611

KHAJURAHO (VEKO)

Caution:
Navblue have identified the following issues with numerous approach transitions at this airport.

IAP ILS RWY 19 and LOC RWY 19 - Transitions D076N, D237O, D324N, KJ, KKJ are incorrect and **should not** be use to fly.
IAP VOR RWY 19 - Transitions D069N , D076N, D105N, D107N, D299N, D304N, D324N are incorrect and **should not** be use to fly.
IAP NDB RWY 19 - all approach transitions are incorrect and **should not** be use to fly, use only final

These changes will be incorporated in NAVBLUE databases for cycle 2612