



JEPPESEN®

Airport Moving Map Alert

!! URGENT !!

Date: 28 September 2026

Subject: Amsterdam, Netherlands
Schiphol (EHAM)
Cycle 2610 and 2611

Aprons P, R and TWYs status incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2610, effective 01 October 2026 and for cycle 2611, effective 29 October 2026 contains incorrect data for Schiphol; Amsterdam, Netherlands (EHAM). Netherlands AIP SUP 30/2025, effective 11 December 2025, introducing Phase 26.1 of “Amsterdam/Schiphol (EHAM): reconstruction of R-apron and adjacent taxiways A, B and Q,” has been prolonged by NOTAM A2169/26, effective 14 September at 06:31 [UTC]. These changes are not reflected in cycle 2610 and 2611 data, as NOTAM A2169/26 was received after the ICAO specified date for aeronautical information publication and does not cover entire AIRAC cycle.

The following changes are valid from 01 October 2026 until 06:00 [UTC] on 16 November 2026:

- Apron P is closed
- Apron R is closed
- TWYs A29, A30 are closed
- TWY P (between TWY B and TWY Z) is closed
- TWYs R, R1-R3 are closed

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2612, effective 26 November 2026. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

EHAM_2610_2611