



JEPPESSEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 19 October 2026

Subject: Khanh Hoa, Vietnam
Cam Ranh Intl (VVCR)
Cycle 2610

RWY 02L/20R status incorrect.

TWYs G3, G5, W, W1, W3, W5, W6, Y5, Y6 status incorrect.

Construction Areas missing.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2610, effective 01 October 2026 contain incorrect data for Cam Ranh Intl; Khanh Hoa, Vietnam (VVCR). Vietnam AIP SUP 55/26, published and effective 12 October 2026, introduces construction of RWY 02L/20R and TWYs. Works occur in phases between 12 October 2026 and 28 October 2026 and are not reflected in cycle 2610 data, as changes do not cover entire AIRAC cycle.

Following changes are valid from 17:00 [UTC] on 12 October 2026 until 16:59 [UTC] on 20 October 2026:

- RWY 02L/20R is closed (except for taxiing)
- TWY W (between TWY W1 and W6) is closed
- TWYs W1, W3, W5, Y5 are closed
- Construction Area on TWY W is added

Following changes are valid from 17:00 [UTC] on 20 October 2026 until 16:59 [UTC] on 24 October 2026:

- RWY 02L/20R is closed (except for taxiing)
- TWY W (between TWY W7 and 140m west of TWY W6) is closed
- TWYs W6, Y6 are closed
- Construction Area on TWY W is added

Following changes are valid from 17:00 [UTC] on 24 October 2026 until 16:59 [UTC] on 28 October 2026:

- RWY 02L/20R is closed (except for taxiing at RWY ends)
- TWYs G3, G5, W3, W5, W6 are closed
- Construction Area on RWY 02L/20R is added

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2611, effective 29 October 2026. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.