



## !! URGENT !!

**Date:** 22 January 2026

**Subject:** Guwahati, India  
Lokpriya Gopinath Bordoloi Intl (VEGT)  
Cycle 2601

***TWYs and Parking Stands Layout incorrect.***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2601, effective 22 January 2026 contain incorrect data for Lokpriya Gopinath Bordoloi Intl; Guwahati, India (VEGT). India AIRAC AIP SUP 242/2025 effective 22 January 2026, introducing "Commissioning of new facilities & other changes Lokpriya Gopinath Bordoloi International Airport (VEGT)" has been postponed per NOTAM G0066/26 and as result following changes were not included in cycle 2601 data:

- Aprons K,T2 are renamed to Apron 2
- TWY A (between Parking Stand 9 and TWY B9) is withdrawn
- TWYs B9, C8, D, D1, D3 are withdrawn
- Parking Stands 21L/R, 22L/R, 24L, 41-43 are withdrawn
- Parking Sands 22-26 are added
- Parking Stand 44 is renamed to 30
- Parking Stand 45 is renamed to 31
- Position Markings Z1, Z2, Z3 are withdrawn
- Terminal 2 is renamed to Terminal T2
- Terminal 1 is renamed to Terminal

### **WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2602, effective 19 February 2026. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:  
**Support Portal:** [digitalsuccess.jeppesen.com](http://digitalsuccess.jeppesen.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.