



!! URGENT !!

Date: 27 January 2026

Subject: Esbjerg, Denmark
Esbjerg (EKEB)
RNP Rwy 26
Cycle 2601

Procedure information incorrect

Jeppesen NavData for cycle 2601, effective 22 January 2026 contains incorrect data for Esbjerg, Denmark (EKEB).

Procedure **RNP Rwy 26**: turn direction for holding **TOMMO** should read **RIGHT**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2602, effective 19 February 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Esbjerg, Denmark (EKEB) chart 12-4, dated 2 MAY 25 (eff 15 May) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

EKEB_2601