

!! URGENT !!

Date: 22 December 2025

Subject: Erzurum, Turkiye

Erzurum Intl (LTCE) Multiple procedures Cycles 2512 & 2513

Procedure information missing

Jeppesen NavData for cycle 2512, effective 27 November 2025, and for cycle 2513, effective 25 December 2025 contains incorrect data for Erzurum Intl; Erzurum, Turkiye (LTCE). Turkiye permanent NOTAM A5676/25, effective 15 December 2025, could not be incorporated in time and contains new instrument approach procedure information.

Procedures ILS V or LOC V Rwy 26R and CAT II/III ILS W Rwy 26R are missing from the database.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2601, effective 22 January 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.