



!! URGENT !!

Date: 08 December 2025

Subject: Richmond, New South Wales, Australia
Richmond (YSRI)
Multiple procedures
Cycle 2512

Procedure information incorrect

Jeppesen NavData for cycle 2512, effective 27 November 2025 contains incorrect data for Richmond, New South Wales, Australia (YSRI).

TACAN Rwy 28 and ILS Y or LOC Y Rwy 28 procedures: approach transition RICHMOND (RIC) should read VOSSI.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2513, effective 25 December 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

YSRI_2512