



JEPPESSEN®

NavData® Alert

!! URGENT !!

Date: 19 January 2026

Subject: Siauliai, Lithuania
Siauliai Intl (EYSA)
Multiple procedures
Cycle 2601

Procedures information incorrect

Jeppesen NavData for cycle 2601, effective 22 January 2026 contains incorrect data for Siauliai Intl; Siauliai, Lithuania (EYSA). Lithuania AIP SUP 01/26 (**effective 05 February 2026**) was received after the ICAO specified date for aeronautical information publication and contains procedure information which could not be incorporated in time.

- **TACAN SQQ** coordinates should read: **N 55° 52' 32.6" E 023°24'48.3"**
- Approach procedures: **ILS Y or LOC Y Rwy 14L, ILS Y or LOC Y Rwy 32R, TACAN Rwy 14L, TACAN Rwy 32R, TACAN Rwy 14R and TACAN Rwy 32L** completely revised, therefore should not be used.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2602, effective 19 February 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.