



Navigation Database Addendum

Friday, 28 November 2025

AIRAC 2512 – Issue 16

Airbus TOS2 incorrect flag

The following runways are **incorrectly flagged as Airbus TOS2 approved** in the Cycle 2512 data:

ENBR RW17
ENBR RW35
LFAQ RW08R
LFAQ RW26L
LFNF RW16
LFNF RW34
LFOK RW10
LFOK RW28
LFSK RW22
LKPD RW09
LKPD RW27
RCMQ RW18
RCMQ RW36
YBDV RW03
YBDV RW21
YBYL RW15
YBYL RW33

Navdata will be updated effective AIRAC cycle 2513.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com