



## Navigation Database Addendum

Tuesday, 03 February 2026

### AIRAC 2601 – Correction 2 to Issue 12

**Source: AIRAC SUP 102/A/25FC, Effective date: 27.11.2025**

**NOTAM FC A0052/26, Effective date: 21.01.2026**

**AIP SUP 10/A/26FC (checklist), Effective date: 30.01.2026**

### FPST Sao Tome Intl

---

**SID: RNP RWY 11/29**

**STAR: RNP RWY 29**

**APCH: RNP RWY 29, VOR RWY 29**

AIRAC SUP 102/A/25FC and NOTAM FC A0052/26 have been cancelled by AIP SUP 10/A/26FC (checklist).

The following procedures in the database are **cancelled** and should not be used:

- RNP SIDs RWY 11/29
- RNP STARs RWY 29
- RNP APCH RWY 29
- VOR APCH RWY 29

Until the database is updated, the following procedures are valid:

- Conventional SIDs RWY 11/29
- APCH VOR 29-T
- APCH NDB 29-T  
(Suffix T is a Lido internal procedure name extension for procedure differentiation in the database and not used by ATC)

Please disseminate this information to all affected crews.

Lufthansa Systems  
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)