



## NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2601-02N

**Notification Published date:** 20-01-2026

**Product Affected:** Navigation+

**AIRAC Cycle:** 2601

**Effective Date:** 22-01-2026

**Region:** SAM

**Country:** Brazil; Colombia

**Subject:** Brazil (SBKP), Colombia (SKCL, SKPP & SKYP)

**Source:** AIRAC AMD MAP 2601A1, AIP Supplement 52/25, 55/25 & 57/25

### Procedure updates:

#### VIRACOPOS (SBKP)

**Please Note:** After confirmation from the state due to a discrepancy in altitude restriction between the chart and coding table, the following changes are required in **NAVBLUE** databases.

##### **SID**

##### **OPGU2A**

Transition ISMOB, missing altitude restriction of minimum FL160 over waypoint KP179 is applicable.

#### ALFONSO BONILLA ARAGON (SKCL)

**Please Note:** After confirmation from the state due to a discrepancy of variation and SID ident. Updated variation and SID ident information has been provided by the State authority. The following changes are required in **NAVBLUE** databases.

##### **SID**

SID ident **TULU1K** has changed to **ULQ1K**.

SID **ASIK1D, TOLI1F, TULU1K** MAG VAR has changed from W7 to W6.

#### GUILLERMO LEON VALENCIA (SKPP)

**Please Note:** The **RNP Y (AR) RWY 08** approach, missed approach waypoint PP403 has been incorrectly coded as a Fly-over waypoint in the **NAVBLUE** databases due to



## NOTIFICATION BULLETIN

discrepancies in state publications.

After confirmation from the state the waypoint PP403 on the missed approach has been confirmed as a Fly-by waypoint.

### APPROACH

#### RNP Y (AR) RWY 08

Missed approach: PP403 should be flyby

### EL ALCARAVAN (SKYP)

**Please Note:** The APCH type for VOR Z RWY 05 is incorrect in **NAVBLUE databases**.

APCH type for VOR Z RWY 05 should be D (VOR/DME required) instead of S (VOR using VORDME/VORTAC).

**These changes will be incorporated into NAVBLUE databases for cycle 2602.**