



JEPPESSEN®

Airport Moving Map Alert

!! URGENT !!

Date: 08 July 2025

Subject: Shanghai, PR of China
Hongqiao (ZSSS)
Cycle 2507

***Construction Area missing.
TWYs D, D14-D16, H5 status incorrect.
Parking Stands 263- 265 status incorrect.***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2507, effective 10 July 2025, contain incorrect data for Hongqiao; Shanghai, PR of China (ZSSS). China AIP SUP 03/25, published 15 February 2025, effective 19 March 2025, is not reflected in cycle 2507 data as do not cover entire AIRAC cycle.

The following changes are valid until 15:59 [UTC] on 31 July 2025:

- Construction Area (on TWY D, between TWY D14 and TWY D16) is added
- TWY D (between TWY D14 and TWY D16) is closed
- TWYs D14-D16 are closed
- Temporary TWY D (between Parking Stand 264 and Parking Stand 290) is added
- TWY H5 is closed
- TWY L13 is removed
- TWY L14 (between Parking Stand 290 and Parking Stand 601) is removed
- Parking Stands 263-265 are closed
- Hot Spots HS4, HS10 are removed
- TWY Holding Positions AP06, AP07, EOT07 are removed
- Low Visibility Procedures are updated

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2508, effective 07 August 2025. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

ZSSS_2507