

!! URGENT!!

Date: 27 March 2025

Subject: Chongqing, PR of China

Jiangbei (ZUCK) Cycle 2503 and 2504

Airport Layout incorrect

Jeppesen Airport Moving Map and A816 formatted data for cycle 2503, effective 20 March 2025 and for cycle 2504, effective 17 April 2025, contain incorrect data for Jiangbei; Chongqing, PR of China (ZUCK). PERM NOTAMs: U1098/25, U1104/25, U1105/25, U1106/25, U1107/25, U1108/25, U1109/25, U1110/25, U1111/25, U1112/25, U1113/25 effective from 09:00 [UTC] on 27 March 2025 put into operation new TWYs and Parking Stands. The following changes are not included in cycle 2503 and 2504 data:

- Construction Area near Terminal T3B is removed
- TWYs E7, E8, E9, E10, E11 (east of TWY E) are added
- TWY F (between TWY Z3 and TWY Z9) is added
- TWY G (between TWY Z5 and TWY Z9) is added
- TWYs H3, G4, G5, G6 (west of TWY H) is added
- TWY M1 (between TWY F and TWY G, north of TWY Z6) is added
- TWYs M2 and M3 are added
- TWY M4 (between TWY F and TWY G, south of TWY Z8) is added
- TWYs P1, P2, P3, P4 are added
- TWYs T5- T10, T11 (south of TWY Z9), T12 are added
- TWY Z4 (between TWY E and Parking Stands 523) is added
- TWY Z5 (between TWY E and TWY G) is added
- TWY Z6, Z8 (between TWY E and TWY H) are added
- Parking Stands 515- 517 are opened
- Parking Stands 541- 556 are added
- Parking Stands 601, 602/R/L, 603, 604, 605/R/L, 606, 607/R/L, 608- 610, 611/R/L, 612/R/L, 613/R/L, 614- 628, 629/R/L, 630, 631/R/L, 632, 633/R/L, 634, 635/R/L, 636- 638, 639/R/L, 640, 641/R/L, 642, 643/R/L, 644/R/L, 645- 657 are added

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com **E-mail:** gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2505, effective 15 May 2025. Until then this Alert will be posted on the Jeppesen Web site: Notices and Alerts. Please refer to the local NOTAMs and Jiangbei, Chongqing, PR of China 10-9C Chart dated 7 MAR 25, effective 19 MAR 25 for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com **E-mail:** gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.