



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 29 April 2025

Subject: Harbin, PR of China
Taiping (ZYHB)
LARUN 11A [LAR11A]
Cycle 2504

Procedure information outdated

Jeppesen NavData for cycle 2504, effective 17 April 2025, contains incorrect data for Taiping; Harbin, PR of China (ZYHB).

STAR LARUN 11A [LAR11A]: coordinates of waypoint **HRB41 (D41.2 HRB)** should read as **N 44° 56' 29.75" E 126° 11' 44.78"**, therefore the procedure should not be used.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2505, effective 15 May 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Taiping, PR of China (ZYHB) 10-2L chart dated 17 JAN 25 (effective 22 Jan 25 1600Z) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

ZYHB_2504