

## Navigation Database Addendum

### **AIRAC 2413 – Issue 12**

**AIRAC AMDT MM 08/24 effective 8th August 2024**

### **MMSM Santa Lucia**

---

#### **Waypoint SM512**

#### **SIDs LORSU 2A RWY 04C and LORSU 2B RWY 04L**

SID LORSU 2A and LORSU 2B:

- coordinates of WPT **SM512** should read **N19-42.7 W098-21.8** (N 19-42-40.5 W 098-21-45.4).

Navdata will be updated effective AIRAC cycle 2502.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 15<sup>th</sup> January 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)

## Navigation Database Addendum

### **AIRAC 2501 – Issue 11**

**AIRAC AMDT MM 01/25 effective 23rd January 2025**

**AIRAC AMDT MM 08/24 effective 8th August 2024**

### **MMSM Santa Lucia**

---

#### **Waypoint SM512**

**SIDs LORSU 2A RWY 04C, LORSU 2B RWY 04L, LORSU 1R RWY 22C and LORSU 1S RWY 22R**

SID LORSU 2A and LORSU 2B:

- coordinates of WPT **SM512** should read **N19-42.7 W098-21.8** (N 19-42-40.5 W 098-21-45.4).

SID LORSU 1R RWY 22C and LORSU 1S RWY 22R are missing in DB.

Navdata will be updated effective AIRAC cycle 2502.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 15<sup>th</sup> January 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)