



Navigation Database Addendum

AIRAC 2310 – Issue 5

SUP SB A051-N116/23 effective 5th October 2023

SB Brazil

Several AWYs

Due to late receipt of document, changes to cruising levels and direction of the following AWYs could not be included in NavDB:

UL304, UL452, UL776, UM417, UM423, UM668, UM775, UN741, UZ2, UZ3, UZ8, UZ12, UZ16, UZ17, UZ19, UZ25, UZ26, UZ30, UZ33, UZ35, UZ38, UZ40, UZ42, UZ59, UZ60, UZ61, UZ70, UZ78, UZ79, UZ80, UZ81, UZ87, UZ88, UZ98.

Navdata will be updated effective AIRAC cycle 2311.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 29th September 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com