

## Navigation Database Addendum

### **AIRAC 2406 – Issue 5**

**AIRAC DAP SUP C14/21 effective 7th October 2021**

### **VVCM Ca Mau**

---

#### **SID TRN 1B**

**SID TRN 1B** RWY 27, speed restriction in initial turn should read "**max. 205KT**".

Navdata will be updated effective AIRAC cycle 2407.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 5<sup>th</sup> June 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)

## Navigation Database Addendum

### **AIRAC 2405 – Issue 15**

**AIRAC DAP SUP C14/21 effective 7th October 2021**

### **VVCM Ca Mau**

---

#### **SID TRN 1B**

**SID TRN 1B** RWY 27, speed restriction in initial turn should read "**max. 205KT**".

Navdata will be updated effective AIRAC cycle 2407.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 5<sup>th</sup> June 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)