

Navigation Database Addendum

AIRAC 2406 – Issue 6

AIRAC AMDT MM 02/23 effective 23rd February 2023

MMTO Toluca Lic Adolfo L Mateos Intl

APCH RNP RWY 33

- ALT at **TO800** should read "**at 10000ft**"
- MUSOS transition: speed at **MUSOS** should read "**at 200KT**"

Navdata will be updated effective AIRAC cycle 2407.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 6th June 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2405 – Issue 16

AIRAC AMDT MM 02/23 effective 23rd February 2023

MMTO Toluca Lic Adolfo L Mateos Intl

APCH RNP RWY 33

- ALT at **TO800** should read "**at 10000ft**"
- MUSOS transition: speed at **MUSOS** should read "**at 200KT**"

Navdata will be updated effective AIRAC cycle 2407.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 6th June 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com