



AN AIRBUS COMPANY

# RECEIVED ON TIME, NOT INCLUDED NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2505-04R

**Notification Published date:** 08-05-2025

**Product Affected:** Navigation+

**AIRAC Cycle:** 2505

**Effective Date:** 15-05-2025

**Region:** SAM

**Country:** Falkland Islands

**Subject:** STANLEY INTL (SFAL)

**Source:** AIP 25/04/17

**Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2505**

## STANLEY INTL (SFAL)

### **Aerodrome Data:**

Airport record: Mag var changed from 2.5° E to 2.2° E

MSA (SFAL) - Bearings changed from 0° to 1°, 90° to 91° and 180° to 181°

**NDB-DME RWY 09** - Revised

Holding Pattern:

Hold on SA NDB (305KHz) - Speed of 210kts removed, course changed from 276 ° to 277°.

**NDB-DME RWY 27** - Revised

**These changes will be incorporated in NAVBLUE databases for cycle 2506**