



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2309-08E

Notification Published date: 20-09-2023

Product Affected: Navigation+

AIRAC Cycle: 2309

Effective Date: 07-09-2023

Region: USA

Country: United States of America

Subject: KCVS : ILS 'IOVI' Incorrect Localizer Bearing

Source: NFDC N/A

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2309

Please be aware: Due to inaccurate state publication, the localizer bearing of KCVS ILS 13 'IOVI' was incorrectly updated to read 135 degrees for cycle 2309. The localizer bearing should read 128 degrees.

These changes will be incorporated in NAVBLUE databases for cycle 2310