



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2310-01E

Notification Published date: 28-09-2023

Product Affected: Navigation+

AIRAC Cycle: 2310

Effective Date: 05-10-2023

Region: AFR

Country: Libya

Subject: HLMS: ILS 33 'IMIS' Incorrect Localizer Longitude

Source: AIRAC Amd 01-23

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2310

Please be aware: Due to inaccurate information published by the state, the localizer Longitude for ILS 'IMIS' has been published incorrectly.
The localizer coordinates should read 'N32-20-27.93 E015-02-53.8' rather than 'N32-20-27.93 E015-02-05.85'

These changes will be incorporated in NAVBLUE databases for cycle 2311