



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2408-01E

Notification Published date: 09-08-2024

Product Affected: Navigation+

AIRAC Cycle: 2408

Effective Date: 08-08-2024

Region: EEU

Country: China

Subject: LIJIANG/SANYI (ZPLJ) - Missed Approach Point incorrectly coded

Source: AIP 240807

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2408

LIJIANG/SANYI (ZPLJ)

Caution: The Missed Approach Point (MD20) for the VOR/DME RWY20 Approach is coded with incorrect coordinates in **NAVBLUE** databases. The coordinates should read N26 45 37.285 E100 16 11.053.

These changes will be incorporated in NAVBLUE databases for cycle 2409