



AN AIRBUS COMPANY

## ERROR NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2412-06E

**Notification Published date:** 03-12-2024

**Product Affected:** Navigation+

**AIRAC Cycle:** 2412

**Effective Date:** 28-11-2024

**Region:** PAC

**Country:** Hong Kong

**Subject:** Incorrect type of BEKOL fix used on VHHH SIDs

**Source:** AIP 241003

**Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2412**

### VHHH Hong Kong International

**Caution:** The following SIDs at VHHH use a terminal fix BEKOL (VHHH) where it should be the enroute fix BEKOL (ZG). Both of the fixes have the same position N22-32-36.00 E114-08-00.00.

BEKO1Z

BEKO5A

BEKO3B

ADLA1T

BEKO1Y

BEKO1D

BEKO1C

BEKO2E



AN AIRBUS COMPANY

## ERROR NOTIFICATION BULLETIN

BEKO1X

**These changes will be incorporated in NAVBLUE databases for cycle 2413**