



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2412-08E

Notification Published date: 04-12-2024

Product Affected: Navigation+

AIRAC Cycle: 2412

Effective Date: 28-11-2024

Region: PAC

Country: Hong Kong

Subject: Incorrect type of BEKOL fix used on VHHH SIDs - Replacement of 2412-06E

Source: AIP 241003

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2412

VHHH Hong Kong International

CAUTION: The Waypoint BEKOL has been duplicated in NAVBLUE Databases.

NAVBLUE databases contains both BEKOL/VHHH and BEKOL/ZG with the same position N22-32-36.00 E114-08-00.00. Whereby:

- VHHH SIDs are using Waypoint BEKOL/VHHH
BEK01Z
BEK05A
BEK03B
ADLA1T
BEK01Y
BEK01D
BEK01C
BEK02E
BEK01X



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

- Airways are using Waypoint BEKOL/ZG

As a result of this, you may encounter discontinuity issues. This issue will be rectified for cycle 2413.

These changes will be incorporated in NAVBLUE databases for cycle 2413