



AN AIRBUS COMPANY

## ERROR NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2503-06E

**Notification Published date:** 25-03-2025

**Product Affected:** Navigation+

**AIRAC Cycle:** 2503

**Effective Date:** 20-03-2025

**Region:** EEU

**Country:** China

**Subject:** LANZHOU/ZHONGCHUAN (ZLLL) - ILS/DME Y RWY 18 & 19

**Source:** AIP Amd 03/25

**Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2503**

### LANZHOU/ZHONGCHUAN (ZLLL)

**CAUTION:** ILS/DME Y RWY 18L & 19 approaches have incorrectly coded transitions in NAVBLUE databases.

#### **ILS/DME Y RWY 18L:**

**Transition DJC** - Fix D6.7 DJC to R354 (24.0) DNC has been coded as DF (direct to fix) leg instead of AF leg (ARC to fix).

**Transition DZH33** - Fix D39.6 DZH to R007 (24.0) DNC has been coded as DF (direct to fix) leg instead of AF leg (ARC to fix).

#### **ILS/DME Y RWY 19:**

**Transition DJC** - Fix D6.7 DJC to R357 (24.0) DNC has been coded as DF (direct to fix) leg instead of AF leg (ARC to fix).

**Transition DZH33** - Fix D39.6 DZH to R010 (24.0) DNC has been coded as DF (direct to fix) leg instead of AF leg (ARC to fix).

**These changes will be incorporated in NAVBLUE databases for cycle 2504**