



AN AIRBUS COMPANY

## ERROR NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2606-03E

**Notification Published date:** 10-06-2026

**Product:** Navigation

**Database Type:**

**AIRAC Cycle:** 2606

**Effective Date:** 11-06-2026

**Region:** EEU

**Country:** China

**Subject:** WUHAN/TIANHE (ZHHH) - SID Waypoint coordinates

**Source:** NOTAM G1695/26

**Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2606**

### WUHAN/TIANHE (ZHHH)

**CAUTION:** The coordinates of the following waypoints are incorrect in NAVBLUE databases:

#### **SIDs**

##### **BIVP5E, OLMB5E, XSH5E, XSH7E**

HH111 coordinates changed from N30 50 08.40 E114 19 46.70 to N30 49 47.80 E114 20 13.60.

HH121 coordinates changed from N30 50 00.60 E114 19 56.90 to N30 49 40.10 E114 20 23.70.

#### **SIDs**

##### **BENB4E, BIVP4E, OLMB4E, XSH4E:**

HH161 coordinates changed from N30 40 26.50 E114 09 45.30 to N30 40 01.80 E114 10 17.70.

HH171 coordinates changed from N30 40 16.40 E114 09 58.50 to N30 39 49.00 E114 10 34.40.

**These changes will be incorporated in NAVBLUE databases for cycle 2607**



AN AIRBUS COMPANY

## **ERROR NOTIFICATION BULLETIN**