



JEPPESEN®

Airport Moving Map Alert

!! URGENT !!

Date: 11 September 2026

Subject: An Giang, Vietnam
Phu Quoc Intl (VVPQ)
Cycle 2609 and 2610

Airport Layout incorrect

Jeppesen Airport Moving Map and A816 formatted data for cycle 2609, effective 03 September 2026 and data for cycle 2510, effective 01 October 2026 contains incorrect data for Phu Quoc Intl; An Giang, Vietnam (VVPQ). Vietnam AIP SUP 49/26 published 10 September 2026, effective 15 September 2026, introducing “Re-designation of the existing Runway 10/28 to 10R/28L and associated flight procedures at Phu Quoc International Airport (VVPQ)” extends construction schedule of the new runway 10L/28R, redesign the existing runway 10/28 to 10R/28L.

The following changes are valid from **15 September until further notice**:

- **RWY 10L/28R is closed**
- TWYs A1, B1, B10, D, D1, D7-D12, D14, S1 and S9 are closed
- Parking Stands 2 and 3A are closed

Per NOTAM A3101/26, the only operational Runway available until 14 September 2026 is RWY 10/28.

Please refer to the following AMM alert for the valid information until 14 September 2026:
“RWY 10/28 information incorrect”.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2611, effective 29 October 2026. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

VVPQ_2609_2610