



# **JEPPESEN<sup>®</sup>**

## ***Airport Moving Map Alert***

**!! URGENT !!**

**Date:** 25 February 2026

**Subject:** Pointe Noire, Rep of Congo  
Antonio Agostinho Neto (FCPP)  
Cycle 2602

***TWY A and Parking Stands status incorrect.***

Jeppesen Airport Moving Map and A816 formatted data for cycle 2602, effective 19 February 2026 contain incorrect data for Antonio Agostinho Neto; Pointe Noire, Rep of Congo (FCPP). AIP SUP NR 16/A/26FC published 20 February 2026, effective 23 February 2026, introducing "Pavement repair work on the apron and taxiway" was received after 2602 AIRAC cycle data processing due date and do not cover entire AIRAC cycle. As a result, the following changes were not included in cycle 2602 data.

*Following changes are valid from 00:00 [UTC] on 23 February 2026 until 23:59 [UTC] on 28 February 2026 (Phase 2):*

- Parking Stands 4A, 4, 4B, 5A are closed

*Following changes are valid from 00:00 [UTC] on 02 March 2026 until 23:59 [UTC] on 10 March 2026 (Phase 3):*

- TWY A is closed

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Jeppesen Airport Moving Map and A816 formatted data for cycle 2602, effective 19 February 2026 will become valid on 11 March 2026. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

**Support Portal:** [digitalsuccess.jeppesen.com](https://digitalsuccess.jeppesen.com)

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.