

## !! URGENT!!

Date: 16 December 2025

Subject: Nancy, France

Ochey (LFSO)

Multiple procedures

**Cycle 2513** 

Procedure information incorrect

Jeppesen NavData for cycle 2513, effective 25 December 2025 contains incorrect data for Ochey; Nancy, France (LFSO). France MIL (MIAC 2) AMDT 001/26 (effective 25 December 2025) was received after the ICAO specified date for aeronautical information publication and contains procedure information which could not be incorporated in time.

- RNAV SID RWY 02: EPL 1N [EPL1N] and MONCE 1N [MONC1N] are missing from the database.
- RNAV SID RWY 20: EPL 1S [EPL1S] and MONCE 1S [MONC1S] are missing from the database.
- Procedures RNP Rwy 02 and RNP Rwy 20 are completely revised, therefore should not be used.

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2601, effective 22 January 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.