



JEPPESEN[®]

NavData[®] Alert

!! URGENT !!

Date: 12 February 2026

Subject: Aswan, Egypt
Aswan Intl (HESN)
Multiple procedures
Cycles 2601 & 2602

Procedures information incorrect

Jeppesen NavData for cycle 2601, effective 22 January 2026, and for cycle 2602, effective 19 February 2026 contains incorrect data for Aswan Intl; Aswan, Egypt (HESN). **EGYPT AIP SUP 22/25** (effective 01 January 2025) was cancelled by **NOTAM A0062/26** (effective 09 February 2026).

The following procedures should not be used:

- RNP Rwy 17L
- RNP Rwy 35R
- VOR Rwy 17L
- VOR Rwy 35R

The following procedures are missing from the database:

- ILS or LOC Rwy 35
- RNP Rwy 17
- RNP Rwy 35
- VOR Rwy 17
- VOR Z Rwy 35
- VOR Y Rwy 35

Runway 17L/35R should not be used and **Runway 17/35** is missing from the database.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jepesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

HESN_2601_2602

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2603, effective 19 March 2026. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Aswan Intl; Aswan, Egypt (HESN) charts 11-1, 12-1, 12-2, 13-1, 13-2 and 13-3, dated 28 JUN 24 (eff 11 Jul) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.