



!! URGENT !!

Date: 5 December 2025

Subject: Campinas, Brazil
Viracopos Intl (SBKP)
RNP W Rwy 33 (AR)
Cycle 2512

Missed Approach Point incorrect

Jeppesen NavData for cycle 2512, effective 27 November 2025, contains incorrect data for Viracopos Intl; Campinas, Brazil (SBKP).

RNP W Rwy 33 (AR) procedure is **not usable**.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2513, effective 25 December 2025. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jepesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

SBKP 2512