

Navigation Database Addendum

Monday, 23 March 2026

AIRAC 2603 – Correction to Issue 5

Source: NOTAM LG B0078 / B0125/26, Effective date: 20.01.2026

LGSR Santorini

Runway: 15/33

Effective 20JAN26 until 20APR26

New RWY 33 threshold coordinates: N36 23.6 E025 28.9 (N36 23 34.74 E025 28 55.38)

Declared distances should read:

RWY 15/33 TORA/TODA/ASDA/LDA 2017m

Vertical guidance for RW33 APCHs should not be used, coded APCHs do not lead to new / displaced threshold.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

Monday, 23 March 2026

AIRAC 2604 – Correction to Issue 1

Source: NOTAM LG B0078 / B0125/26, Effective date: 20.01.2026

LGSR Santorini

Runway: 15/33

Effective 20JAN26 until 20APR26

New RWY 33 threshold coordinates: N36 23.6 E025 28.9 (N36 23 34.74 E025 28 55.38)

Declared distances should read:

RWY 15/33 TORA/TODA/ASDA/LDA 2017m

Vertical guidance for RW33 APCHs should not be used, coded APCHs do not lead to new / displaced threshold.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com