



AN AIRBUS COMPANY

RECEIVED ON TIME, NOT INCLUDED NOTIFICATION BULLETIN

NAVBLUE Reference: 2601-02R

Notification Published date: 21-01-2026

Product Affected: Navigation+

AIRAC Cycle: 2601

Effective Date: 22-01-2026

Region: EEU

Country: Azerbaijan

Subject: Multiple changes in Azerbaijan (UBBB, UBBG & UBLC)

Source: AIRAC Amd 01/26

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2601

ENR Data:

DVOR/DME-GND:

Station Declination updated to 07° E

HEYDAR ALIYEV INTL (UBBB)

Aerodrome Data:

RWY 16: THR elev changed from 4ft to 5ft, TDZE Elev changed from 4ft to 5ft.

RWY 34: THR elev changed from -16ft to -18ft.

ILS 16 IBI: G/S elev changed from 4ft to 5ft.

Procedure Data:

APPROACH

ILS RWY 16, RNP RWY 16 :

MAPT altitude updated to AT 60ft.

ILS RWY 34, RNP RWY 34

MAPT altitude updated to AT 37ft.

GANJA (UBBG)



AN AIRBUS COMPANY

RECEIVED ON TIME, NOT INCLUDED NOTIFICATION BULLETIN

Aerodrome Data:

Airport record: Mag variation changed from 6E to 7E.

RWY 12: Mag bearing changed from 122 to 121

RWY 30: Mag bearing changed from 302 to 301

ILS 12 IGL: Station declination changed from 6E to 7E, LOC bearing changed from 122 to 121.

ILS 30 IGR: Station declination changed from 6E to 7E, LOC bearing changed from 302 to 301.

ILS/DME 12 IGL: Station declination changed from 6E to 7E

ILS/DME 30 IGR: Station declination changed from 6E to 7E

Procedure Data:

SID

EDAT3A, VERC1A, POLA3A, VERC1B, POLA2B, EDAT3B:

All courses have decreased by 001°.

PEMA2A, PEMA1B

All courses have decreased by 001°.

Waypoint renamed from D228Q to D227Q.

MATA2A, MATA1B

All courses have decreased by 001°.

Waypoint renamed from D266P to GND16.

GND16: N40 45 39.441 E045 56 25.213

STAR

MATA1E, MATA1F:

Waypoint D266P replaced with GND16.

GND16: N40 45 39.441 E045 56 25.213

PEMA1E, PEMA1F:

Waypoint D228Y renamed to D227Y.

Waypoint D228Q renamed to D227Q.

APPROACH

ILS RWY 12:

All courses are decreased by 001°.

Waypoint D302O renamed to D301O.

Waypoint D302H renamed to D301H.

ILS RWY 30:

All courses have decreased by 001°.

GND12: N40 39 01.388 E046 30 25.769

VOR/DME RWY 12:

All courses have decreased by 001°.



AN AIRBUS COMPANY

RECEIVED ON TIME, NOT INCLUDED NOTIFICATION BULLETIN

Waypoint D302O renamed to D301O.
Waypoint D302H renamed to D301H.
MD12: N40 45 27.449 E046 17 18.876
MAPT altitude updated to AT 1404 ft.

Holding Pattern:

GND VORDME (Freq: 115.8 MHZ)
Airspace 3 course changed from 266° to 265°.
Airspace 4 and 5 course changed from 302° to 301°.
Airspace 4 and 5 course changed from 122° to 121°.

LACHIN (UBLG)

Aerodrome Data:

Airport record: TL added as FL120
MSA (ARP): New added
ILS/DME 32 ILN: Station declination changed from 6.5E to 6E

Procedure Data:

The following procedures have been established (New):

SID

FZL1A

STAR

FZL1D

APPROACH

RNP RWY 32 (AR)

ILS RWY 32

These changes will be incorporated in NAVBLUE databases for cycle 2602.

These changes will be incorporated in NAVBLUE databases for cycle 2602