



!! URGENT !!

Date: 25 April 2025

Subject: Freetown, Sierra Leone
Lungi (GFLL)
ILS Rwy 30
Cycle 2504

Procedure information incorrect

Jeppesen NavData for cycle for cycle 2504, effective 17 April 2025, contains incorrect data for Lungi; Freetown, Sierra Leone (GFLL).

ILS Rwy 30: GS Intercept altitude should read as 2000', and altitude at fix FI30 should read as 1968'.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2505, effective 15 May 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: support.jeppesen.com

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

GFLL_2504