

Navigation Database Addendum

AIRAC 2501 – Issue 21

SUP 12/2023 effective 11th April 2023

SUP 04/2024 effective 25th January 2024

FZIC Kisangani Bangoka Intl

Runways 12, 30

RWY 12 temporarily displaced by **750m**.

RWY 30 temporarily displaced by **940m**.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 22nd January 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com