



Flight Safety Alert

AIRAC 2307 – Issue 2

NOTAM FDC 3/0755 effective 15th June 2023

KEWR Newark Liberty Intl

APCH RNAV (GPS) RWY 11

Missed approach should read: Climbing RIGHT turn to **3000** direct DIRMY and hold (RT, 061 inbound)

Navdata will be updated effective AIRAC cycle 2308.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 18th July 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com