

# Navigation Database Addendum

### AIRAC 2309 – Issue 4

NOTAM UE C4042/23 effective 23rd August 2023

## **UERP Poliarny**

### All APCHs for RWY 35, Runway 17/35

- Effective 07SEP23 until **26SEP23 1200**, **RWY 35 landing threshold is displaced by 1650 meters towards ARP**, RWY 17/35 **operating length should read 1450 meters**, RWY 35 landing threshold elev. should read 1654 ft., displaced landing threshold coordinates should read **N66-24-04.15 E112-01-46.05**.
- Vertical guidance for RWY 35 APCHs **should not** be used, coded APCHs **do not** lead to the RWY 35 displaced landing threshold.

#### Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Friday, 1<sup>st</sup> September 2023

All valid FSAs/NDAs are available on <u>http://fms-info.lhsystems.com</u> For any inquiries, please contact <u>fms.support@lhsystems.com</u>