



Navigation Database Addendum

AIRAC 2310 – Issue 12

NOTAM A3339/23 MUHG effective 12th September 2023

MUHG Holguin Frank Pais Intl

RWY 05 DTHR

RWY 05 THR displacement of 100m is **not included** in NavDB.

Vertical guidance should not be used.

Coded APCHs do not lead to THR.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 10th October 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com