

Navigation Database Addendum

AIRAC 2405 – Issue 13

AIP HE ENR 3.1-28 effective 8th September 2022

SUP HE 44/24 effective 1st May 2024

HECC Cairo FIR

AWY W976

Disregard discontinuity in AWY W976 between DATOK and TAKSU.

Routing should read "SISIK-VUTAR-**DATOK-TAKSU**-TBA".

Navdata will be updated effective AIRAC cycle 2406.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 30th May 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com