

# **Navigation Database Addendum**

AIRAC 2407 – Issue 13
AIP MDPC AD 2-35-3 effective 16th June 2022

## **MDPC Higuey Punta Cana Intl**

### **APCH VOR/DME RWY 09**

MISAP end ALT at WPT BOTEB should read at 2000ft.

Navdata will be updated effective AIRAC cycle 2408.

### Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Tuesday, 9<sup>th</sup> July 2024

All valid FSAs/NDAs are available on <a href="http://fms-info.lhsystems.com">http://fms-info.lhsystems.com</a>
For any inquiries, please contact <a href="mailto:fms.support@lhsystems.com">fms.support@lhsystems.com</a>



# **Navigation Database Addendum**

AIRAC 2406 – Issue 23
AIP MDPC AD 2-35-3 effective 16th June 2022

### **MDPC Higuey Punta Cana Intl**

#### **APCH VOR/DME RWY 09**

MISAP end ALT at WPT BOTEB should read at 2000ft.

Navdata will be updated effective AIRAC cycle 2408.

#### Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Tuesday, 9<sup>th</sup> July 2024

All valid FSAs/NDAs are available on <a href="http://fms-info.lhsystems.com">http://fms-info.lhsystems.com</a>
For any inquiries, please contact <a href="mailto:fms.support@lhsystems.com">fms.support@lhsystems.com</a>