

## **Navigation Database Addendum**

## **AIRAC 2411 – Issue 12**

NOTAM RK A1509/24 effective 29th October 2024

## RKJB Muan Muan Intl. RK Republic of Korea

## **Runway RWY 19**

Due to late receipt of postponement notification, THR displacement is invalid.

RWY 19 THR coordinates should read N35-00-14.49 E126-22-57.82

Declared distances should read:

RWY 01: TORA/ASDA/LDA 2800 meters; TODA 3000 meters RWY 19: TORA/ASDA/LDA 2800 meters; TODA 3000 meters TWY E2: TORA/ASDA 2057 meters; TODA 2257 meters

Following procedures are not updated in database:

RNP RWY 19 VOR RWY 19

Navdata will be updated effective AIRAC cycle 2412.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Wednesday, 30th October 2024

All valid FSAs/NDAs are available on <a href="http://fms-info.lhsystems.com">http://fms-info.lhsystems.com</a>
For any inquiries, please contact <a href="mailto:fms.support@lhsystems.com">fms.support@lhsystems.com</a>