

Navigation Database Addendum

AIRAC 2504 – Issue 7

SUP ASECNA 64/A/24FC effective 12th December 2024

FOON Franceville M'vengue

Runway 15/33

Due to pavement damage 600m from THR RWY 15, RWY 15 is closed and RWY 33 is shortened by 600m temporarily until 31-DEC-2025.

Declared distances should read:

RWY 15 TORA/TODA/ASDA/LDA NIL

RWY 33 TORA/TODA/ASDA/LDA 2480m

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 11th April 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2505 – Issue 1

SUP ASECNA 64/A/24FC effective 12th December 2024

FOON Franceville M'vengue

Runway 15/33

Due to pavement damage 600m from THR RWY 15, RWY 15 is closed and RWY 33 is shortened by 600m temporarily until 31-DEC-2025.

Declared distances should read:

RWY 15 TORA/TODA/ASDA/LDA NIL

RWY 33 TORA/TODA/ASDA/LDA 2480m

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 11th April 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com