



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2305-01E

Notification Published date: 11-05-2023

Product Affected: Navigation+

AIRAC Cycle: 2305

Effective Date: 18-05-2023

Region: PAC

Country: Thailand

Subject: Chiang Mai International Airport (VTCC)

Source: AIP 230518 AIP

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2305

CHIANG MAI INTERNATIONAL AIRPORT (VTCC)

CAUTION: ILS Y RWY 36 Approach is not included in the NAVBLUE DATABASES for Cycle 2305.

These changes will be incorporated in NAVBLUE databases for cycle 2306